
Cold Peak Polar Sleeping Bag Product Archives







Comfortable temperature

Comfort range -10°C
14°F

Transition range

Limit temperature
-15°C
5°F

Limit range

Extreme temperature -26°C -14.8°F











